

HEIDENHAIN LC495P ML420, ID 1139482-09 Faulty? Position Error? Need Health Check? Get Signal Testing | Wiring | Repair | Troubleshooting Support

Heidenhain

**Did your Encoder stopped working?
Get Checked if Encoder is *Faulty***

**Order Replacement
Encoders | Cables |
Connectors**

**Memory Programming
Parametrization
Wiring at your site**

**Order :: Replacement~ Equivalent
Encoder Health Checking Service- Field
service Support**

encdubai@gmail.com

971-50 9776168

HEIDENHAIN LC495P ML420 | 11 13 94 -09 Id.Nr. 113 948 -09 Failed ? Local repair & Service Field Support for Signal /Wiring/Parameterisation Troubleshooting Order Equivalent

Rating: Not Rated Yet

Price

24 h

★★★★★

[Ask a question about this product](#)

Description :: We offer resolver/Encoder Signal Health Testing for HEIDENHAIN_LC495P ML420, ID 1139482-09, In case you Suspect HEIDENHAIN Absolute encapsulated length measuring instrument with small-profile scale housing_LC495P ML420 | 11 13 94 -09 Id.Nr. 113 948 -09 is somehow behaving erratically, Throwing error, PLC and HMI are showing errors that are often Vague | but may be they give some indication to its being faulty. But is it REALLY FAULTY.. using Multimeter you can not really Make sure of that.. So Make sure that it is Working or Faulty. Normal Maintenance departments do not have tools to check precision sensors like these, We Have invested in Specialised equipment for checking the Signals and Checking its Correct Working - as per output interface :: Count Per Revolution, Reference Pulse, Pulse count, Amplitude & more, send your Unit for Testing/ and we report to you if the unit is working or not if the problem is because of this sensor or not . this is great help in troubleshooting. Many cases you Just suspect the unit is faulty and order replacemnet when exchange is done.. you find problem was really NOT related to sensor.. so avoid such situations get unit inspected prior to ordering. We can also supply this unit and / or its equivalent from stock here or can arrange it quicker then anyone here in Dubai * : Available HEIDENHAIN 7684 Datasheet | Wiring Instructions Available Service Manual," * We Troubleshoot HEIDENHAIN LC495P ML420, ID 1139482-09 installations at your site | We Setup Encoder working with Inverters | Drives | Control Systems * : We can supply you Replacement HEIDENHAIN LC495PML420 | 113948209

Absolute encapsulated length measuring instrument with small-profile scale housing , " * : >>> . Interface: Panasonic Pana01. , " * : >>> Measuring length: 420 mm. , " * : >>> Overall length: ML + 138 mm. , " * : >>> Measuring step: 10 nm. , " * We carry out New installations & Parameterisations for | for various PLC-CNC Systems * Ask for Field Service Visit for - Replacements | New installations of | for various PLC-CNC Systems * if you need any Cable | Connector for connecting your | Contact us we have large inventory of Cables and Connectors, We Supply Cables exactly are as per Machine Manufacturer | OEM guidelines * Contact us for your specific Heidenhain encoder cable with Motor specification sticker details of HEIDENHAIN LC495P ML420 | 11 13 94 -09 Id.Nr. 113 948 -09 and details of Control system / Servo motor where you intend to use it. or are using it. We shall support you with Spares, Services, Upgrades and Equivalent replacements at your site{"@context": "https://schema.org/", "@type": "Product", "name": "HEIDENHAIN LC495P ML420, ID 1139482-09 Faulty? Position Error? Need Health Check? Get Signal Testing | Wiring | Repair | Troubleshooting Support", "image": "https://instockspares.com/images/stories/virtuemart/product/Heidenhain%20encoder%20stopped%20working%20failed%20-%20Get%20checked%20buy%20replacmenet%20.jpg", "sku": "H01P3523", "brand": {"@type": "Brand", "name": "Heidenhain"}, "description": "HEIDENHAIN LC495P ML420 | 11 13 94 -09 Id.Nr. 113 948 -09 Failed ? Local repair & Service Field Support for Signal /Wiring/Parameterisation Troubleshooting Order Equivalent", "category": "Troubleshooting Tools", "offers": {"@type": "Offer", "url": "https://instockspares.com/heidenhain-lc495p-ml420-id-1139482-09-faulty-position-error-need-health-check-get-signal-testing-wiring-repair-troubleshooting-support-detail", "priceCurrency": "USD", "price": 98, "availability": "https://schema.org/InStock"}}

Why Buy From Instock Spares?

- Dubai / UAE based industrial automation spare parts supplier
- Ready stock on many listed items, subject to prior sale
- Same-day dispatch available on confirmed stock items
- Worldwide shipping with express courier options
- Technical support and troubleshooting assistance available
- Field service support available on request
- Trusted industrial supplier since 2003

Frequently Asked Questions

Is this item available in stock?

Many listed items are available from Dubai / UAE stock. Availability is subject to prior sale, so please contact us by WhatsApp, phone, or email to confirm current stock before ordering.

Do you ship internationally?

Yes. We stock and ship industrial automation spare parts worldwide using express courier options.

Can you support installation or troubleshooting?

Yes. Technical support and field service options are available for purchased items upon request.

Can I get an equivalent or upgraded model?

Yes. Contact us with your part number, machine details, or photos, and we will help check compatibility, replacement options, or upgraded models.

Can I cancel or modify an order after it has been placed?

Yes, where possible. Please contact us as soon as possible with your order details. We will assist based on the order status, packing status, and shipment status.

Can I return or exchange a product?

Returns or exchanges may be possible depending on the product type, condition, and order terms. Please review our return policy or contact our team before ordering if you need confirmation.